



QUICK GUIDE VT



acoem

1



2




Machine Defender




3




4



5




6



7

S/N: 20145



**"WLS_12345" Is Not
Connected to the Internet**
Are you sure you want to use this
network?

Join Anyway


Cancel





8




9




10



11




12




13




14



15




16



17



18




19




20



21




22







23




24




25




26




27




28




29




30




31




32




33



34



35





www.fixturlaser.com/downloads/manuals



200 chemin des Ormeaux, 69578 Limonest Cedex, FRANCE

Tel: +33 4 72524800

E-mail: info@acoem.com www.acoem.com